

## STANDARDS CHANGES CATALOG (SCC)

SCC NUMBER: SCC #154

CHANGE PROPOSAL TITLE: Source Address Clarification, Paragraph  
5.3.4.2.2.2.1.1

ORIGINATOR and ADDRESS: ChingLan Lin  
Northrop Grumman MS  
17 Christopher Way  
Eatontown, NJ 07724  
[chinglan.lin@mail1.monmouth.army.mil](mailto:chinglan.lin@mail1.monmouth.army.mil)  
732-532-9874 DSN: 992

ORIGINATOR'S INTERNAL NUMBER:

AFFECTED DOCUMENT: MIL-STD-188-220C, Paragraph 5.3.4.2.2.2.1.1

PRECEDENCE: Routine

RECOMMENDATIONS:

### RECORD OF PROCESSING

| <u>DATE:</u>     | <u>ACTION:</u>                             |
|------------------|--|
| <u>22 Jan 04</u> | <u>Proposal/Work Item</u>                  |
| <u>29 Jan 04</u> | <u>Draft/Approved for MIL-STD-188-220C</u> |

1. STATEMENT OF THE PROBLEM:  
The Source Address described in Paragraph 5.3.4.2.2.2.1.1 is not described correctly.
2. PROBLEM ANALYSIS:  
The sentence "Its legal values range from 1 to 95 for single octet format." in Paragraph 5.3.4.2.2.2.1.1 is not described correctly.
3. PROPOSED SOLUTION:  
  
Change the sentence "Its legal values range from 1 to 95 for single octet format." in Paragraph 5.3.4.2.2.2.1.1 to "Its legal values range from 1 to 95, excluding 3 for single octet format.".
4. ALTERNATIVE SOLUTIONS: None.
5. SYSTEM CHANGES REQUIRED: None.
6. CONFIGURATION ITEM DOCUMENTATION CHANGES:  
MIL-STD-188-220C, Paragraph 5.3.4.2.2.2.1.1.
7. IMPACT ON INTEROPERABILITY: None.
8. IMPACT ON RELATED DOCUMENTS: None.
9. IMPLEMENTATION DATES: ~~TBD~~ Upon approval of the SCC.
10. OTHER CONSIDERATIONS: None.
11. REFERENCES: None.
12. Trouble Reports (TRs) ADDRESSED IN THIS SCC: None.